



DieselTest

Pump info

Part number: 0445010142
Test type: CR/CP1H3/R70/10-89S
Steps: 18
Swap pressuare, kPa: 450
Reverse pressuare, kPa: 50

Client profile

Client info

Name ...

Plate ...

Result

Clean run

Supply 12V; Rotation R; Pressuare 0 MPa; Speed 1500 RPM;

Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;

Flow 1 0

Flow 2 0

Warm up

Supply 12V; Rotation R; Pressuare 25 MPa; Speed 2700 RPM;

Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;

Flow 1 0

Flow 2 0

zme takt. 1

Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM;

Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;

Flow 1 0

Flow 2 0

zme takt. 2	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM; Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 1 0 Flow 2 0
zme takt. 3	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM; Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 1 0 Flow 2 0
zme takt. 4	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM; Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 1 0 Flow 2 0
zme takt. 5	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM; Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 1 0 Flow 2 0
zme takt. 6	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM; Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 1 0 Flow 2 0
zme takt.7	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM; Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 1 0 Flow 2 0

zme takt.8	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM;	Flow 1 0
	Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

zme takt.9	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM;	Flow 1 0
	Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

zme takt.10	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM;	Flow 1 0
	Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

zme takt.11	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM;	Flow 1 0
	Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

zme takt.12	Supply 12V; Rotation R; Pressuare 0 MPa; Speed 2500 RPM;	Flow 1 0
	Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

kenn . 2	Supply 12V; Rotation R; Pressuare 50 MPa; Speed 2700 RPM;	Flow 1 0
	Flow 1 Max 118.4; Flow 1 Min 85.6; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

kenn . 3	Supply 12V; Rotation R; Pressuare 50 MPa; Speed 2700 RPM;	Flow 1 0
	Flow 1 Max 75.3; Flow 1 Min 47.9; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

kenn . 4	Supply 12V; Rotation R; Pressuare 50 MPa; Speed 2700 RPM;	Flow 1 0
	Flow 1 Max 27; Flow 1 Min 6.8; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

Relax	Supply 12V; Rotation R; Pressuare 20 MPa; Speed 500 RPM;	Flow 1 0
	Flow 1 Max 0; Flow 1 Min 0; Flow 2 Max 0; Flow 2 Min 0;	Flow 2 0

